

NUC131 Board Supporting Package Directory Introduction

Rev.3.00.005

Directory Information

Document	Driver reference manual and revision history.
Library	Driver header and source files.
SampleCode	Driver sample code.

Document Information

BSP Revision History	Show all the revision history about specific BSP.
Driver Reference Guide	Describe the definition, input and output of each API.

Library Information

CMSIS	CMSIS definitions by ARM® Corp.
Device	CMSIS compliant device header file.
StdDriver	All peripheral driver header and source files.

Sample Code Information

\SampleCode\ISP	Sample codes for In-System-Programming.
\SampleCode\Template	Software Development Template.
\SampleCode\Semihost	Show how to debug with semi-host message print.
\SampleCode\RegBased	The sample code able to access control registers directly.
\SampleCode\StdDriver	Driver Samples

\SampleCode\ISP

ISP_CAN	In-System-Programming Sample code through CAN interface.
ISP_I2C	In-System-Programming Sample code through I2C interface.
ISP_RS485	In-System-Programming Sample code through RS485 interface.
ISP_SPI	In-System-Programming Sample code through SPI interface.
ISP_UART	In-System-Programming Sample code through UART interface.

\SampleCode\RegBased

ADC_ContinuousScanMode	Perform A/D Conversion with ADC continuous scan mode.
ADC_MeasureAVDD	Measure AVDD voltage by ADC.
ADC_PwmTrigger	Demonstrate how to trigger ADC by PWM.
ADC_ResultMonitor	Monitor the conversion result of channel 2 by the digital compare function.
ADC_SingleCycleScanMode	Perform A/D Conversion with ADC single cycle scan mode.
ADC_SingleMode	Perform A/D Conversion with ADC single mode.
BPWM_Capture	Capture the BPWM1 Channel 0 waveform by BPWM0 Channel 0.
BPWM_DoubleBuffer	Change duty cycle and period of output waveform by BPWM Double Buffer function.
CAN_Set_MaskFilter	Use MaskFilter to receive message in Normal mode. This sample code needs to work with CAN_Test_MaskFilter.
CAN_Test_MaskFilter	Use message object No.1 to send message objects (ID=0x700~0x70F). This sample code needs to work with CAN_Set_MaskFilter.
FMC_IAP	Show how to call LDROM functions from APROM. The code in APROM will look up the table at 0x100E00 to get the address of function of LDROM and call the function.
FMC_MultiBoot	Implement a multi-boot system to boot from different applications in APROM. A LDROM code and 4 APROM code are implemented in this sample code.
FMC_RW	Show how to read/program embedded flash by ISP function.
GPIO_EINTAndDebounce	Show the usage of GPIO external interrupt function and debounce function.
GPIO_INT	Show the usage of GPIO interrupt function.

GPIO_OutputInput	Show how to set GPIO pin mode and use pin data input/output control.
GPIO_PowerDown	Show how to wake up system from Power-down mode by GPIO interrupt.
I2C_EEPROM	Show how to use I ² C interface to access EEPROM.
I2C_GCMode_Master	Show how a Master uses I ² C address 0x0 to write data to Slave. This sample code needs to work with I2C_GCMode_Slave.
I2C_GCMode_Slave	Show a Slave how to receive data from Master in GC (General Call) mode. This sample code needs to work with I2C_GCMode_Master.
I2C_Master	Show a Master how to access Slave. This sample code needs to work with I2C_Slave.
I2C_Slave	Show how to set I ² C in Slave mode and receive the data from Master. This sample code needs to work with I2C_Master.
I2C_Wakeup_Master	Show how to wake up MCU from Power-down. This sample code needs to work with I2C_Wakeup_Slave.
I2C_Wakeup_Slave	Show how to wake up MCU from Power-down mode through I ² C interface. This sample code needs to work with I2C_Wakeup_Master.
PWM_Capture	Capture the PWM1 Channel 0 waveform by PWM0 Channel 0.
PWM_DeadZone	Demonstrate how to use PWM Dead Zone function.
PWM_DoubleBuffer	Change duty cycle and period of output waveform by PWM Double Buffer function.
SPI_Loopback	Implement SPI Master loop back transfer. This sample code needs to connect SPI0_MISO0 pin and SPI0_MOSIO pin together. It will compare the received data with transmitted data.

SPI_MasterFifoMode	Configure SPI0 as Master mode and demonstrate how to communicate with an off-chip SPI Slave device. This sample code needs to work with SPI_SlaveFifoMode sample code.
SPI_SlaveFifoMode	Configure SPI0 as Slave mode and demonstrate how to communicate with an off-chip SPI Master device. This sample code needs to work with SPI_MasterFifoMode sample code.
SYS_PLLClockOutput	Change system clock to different PLL frequency and output system clock from CLK0 pin.
TIMER_Capture	Show how to use the timer0 capture function to capture timer0 counter value
TIMER_Counter	Implement timer0 event counter function to count the external input event.
TIMER_PeriodicINT	Implement timer counting in periodic mode.
TIMER_PowerDown	Use timer0 periodic time-out interrupt event to wake up system.
UART_AutoFlow_Master	Transmit and receive data with auto flow control. This sample code needs to work with UART_AutoFlow_Slave.
UART_AutoFlow_Slave	Transmit and receive data with auto flow control. This sample code needs to work with UART_AutoFlow_Master.
UART_IrDA_Master	Transmit and receive data in UART IrDA mode. This sample code needs to work with UART_IrDA_Slave.
UART_IrDA_Slave	Transmit and receive data in UART IrDA mode. This sample code needs to work with UART_IrDA_Master.
UART_LIN	Transmit LIN header and response.
UART_RS485_Master	Transmit and receive data in UART RS485 mode. This sample code needs to work with UART_RS485_Slave.
UART_RS485_Slave	Transmit and receive data in UART RS485 mode. This sample code needs to work with UART_RS485_Master.

UART_TxRx_Function	Transmit and receive data from PC terminal through RS232 interface.
WDT_PowerDown	Use WDT time-out interrupt event to wake-up system.
WDT_TimeoutINT	Implement periodic WDT time-out interrupt event.
WDT_TimeoutReset	Show how to generate time-out reset system event while WDT time-out reset delay period expired.
WWDT_CompareINT	Show how to reload the WWDT counter value.

\SampleCode\StdDriver

ADC_ContinuousScanMode	Perform A/D Conversion with ADC continuous scan mode.
ADC_MeasureAVDD	Measure AVDD voltage by ADC.
ADC_PwmTrigger	Demonstrate how to trigger ADC by PWM.
ADC_ResultMonitor	Monitor the conversion result of channel 2 by the digital compare function.
ADC_SingleCycleScanMode	Perform A/D Conversion with ADC single cycle scan mode.
ADC_SingleMode	Perform A/D Conversion with ADC single mode.
BPWM_Capture	Capture the BPWM1 Channel 0 waveform by BPWM0 Channel 0.
BPWM_DoubleBuffer	Change duty cycle and period of output waveform by BPWM Double Buffer function.
CAN_BasicMode_Receive	Implement receive message in Basic mode. This sample code needs to work with CAN_BasicMode_Transmit.
CAN_BasicMode_Transmit	Implement transmit message in Basic mode. This sample code needs to work with CAN_BasicMode_Receive.
CAN_NormalMode_Receive	Implement receive message in Normal mode. This sample code needs to work with CAN_NormalMode_Transmit.

© 2015 Nuvoton Technology Corp.

CAN_NormalMode_Transmit	Implement transmit message in Normal mode. This sample code needs to work with CAN_NormalMode_Receive.
CAN_Wakeup	Show how to wake up system form Power-down mode by detecting a transition.
DAC_PWMTrigger	Demonstrate how to trigger DAC by PWM.
DAC_SoftwareTrigger	Demonstrate how to trigger DAC conversion by software method.
DAC_TimerTrigger	Demonstrate how to trigger DAC by timer.
FMC_IAP	Show how to reboot to LDROM functions from APROM. This sample code set VECMAP to LDROM and reset to re-boot to LDROM.
FMC_RW	Show how to read/program embedded flash by ISP function.
GPIO_EINTAndDebounce	Show the usage of GPIO external interrupt function and debounce function.
GPIO_INT	Show the usage of GPIO interrupt function.
GPIO_OutputInput	Show how to set GPIO pin mode and use pin data input/output control.
GPIO_PowerDown	Show how to wake up system from Power-down mode by GPIO interrupt.
I2C_EEPROM	Show how to use I ² C interface to access EEPROM.
I2C_GCMode_Master	Show how a Master uses I ² C address 0x0 to write data to Slave. This sample code needs to work with I2C_GCMode_Slave.
I2C_GCMode_Slave	Show a Slave how to receive data from Master in GC (General Call) mode. This sample code needs to work with I2C_GCMode_Master.
I2C_Master	Show a Master how to access Slave. This sample code needs to work with I2C_Slave.

I2C_Slave	Show how to set I ² C in Slave mode and receive the data from Master. This sample code needs to work with I2C_Master.
I2C_Wakeup_Master	Show how to wake up MCU from Power-down. This sample code needs to work with I2C_Wakeup_Slave.
I2C_Wakeup_Slave	Show how to wake up MCU from Power-down mode through I ² C interface. This sample code needs to work with I2C_Wakeup_Master.
PWM_Capture	Capture the PWM1 Channel 0 waveform by PWM0 Channel 0.
PWM_DeadZone	Demonstrate how to use PWM Dead Zone function.
PWM_DoubleBuffer	Change duty cycle and period of output waveform by PWM Double Buffer function.
SPI_Loopback	Implement SPI Master loop back transfer. This sample code needs to connect SPI0_MISO0 pin and SPI0_MOSI0 pin together. It will compare the received data with transmitted data.
SPI_MasterFifoMode	Configure SPI0 as Master mode and demonstrate how to communicate with an off-chip SPI Slave device. Needs to work with SPI_SlaveFifoMode sample code.
SPI_SlaveFifoMode	Configure SPI0 as Slave mode and demonstrate how to communicate with an off-chip SPI Master device. This sample code needs to work with SPI_MasterFifoMode sample code.
SYS_PLLClockOutput	Change system clock to different PLL frequency and output system clock from CLKO pin.
TIMER_Capture	Show how to use the timer0 capture function to capture timer0 counter value.
TIMER_Counter	Implement timer0 event counter function to count the external input event
TIMER_Delay	Show how to use timer0 to create various delay time.

TIMER_PeriodicINT	Implement timer counting in periodic mode.
TIMER_PowerDown	Use timer0 periodic time-out interrupt event to wake up system.
UART_Autoflow_Master	Transmit and receive data with auto flow control. This sample code needs to work with UART_Autoflow_Slave.
UART_Autoflow_Slave	Transmit and receive data with auto flow control. This sample code needs to work with UART_Autoflow_Master.
UART_IrDA_Master	Transmit and receive data in UART IrDA mode. This sample code needs to work with UART_IrDA_Slave.
UART_IrDA_Slave	Transmit and receive data in UART IrDA mode. This sample code needs to work with UART_IrDA_Master.
UART_LIN	Transmit LIN header and response.
UART_RS485_Master	Transmit and receive data in UART RS485 mode. This sample code needs to work with UART_RS485_Slave.
UART_RS485_Slave	Transmit and receive data in UART RS485 mode. This sample code needs to work with UART_RS485_Master.
UART_TxRx_Function	Transmit and receive data from PC terminal through RS232 interface.
WDT_PowerDown	Use WDT time-out interrupt event to wake-up system.
WDT_TimeoutINT	Implement periodic WDT time-out interrupt event.
WDT_TimeoutReset	Show how to generate time-out reset system event while WDT time-out reset delay period expired.
WWDT_CompareINT	Show how to reload the WWDT counter value.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*